






I = Inspected NI = Not Inspected NP = Not Present R = Repair Needed D = Defective					Item	Condition
					Comments	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Siding	Acceptable
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Fascia, soffits, trim	Damaged but operational
					Door casing has been hit with vehicle and has been knocked slightly out of alignment. Reference Pictures: CIMG4171	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Service Door(s)	Acceptable
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Window(s)	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Overhead door(s)	Acceptable
					All safety features of the door functioned as designed.	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Safety eye(s)	Functional
					No problems. Safety eyes worked fine and stopped door when beam was interrupted.	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Water faucets	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Window wells, crawl space vents	

Photos and Additional Comments

Trim: Functional, but junction between bricks and door casing should be resealed.