

I = Inspected NI = Not Inspected NP = Not Present R = Repair Needed D = Defective					
I	NI	NP	R	D	Item
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Master bedroom Doors and windows Sliding double door functions and poses no problems.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Master bedroom Floor Floor is carpeted and is in good condition. Room has both input and return HVAC vents.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Master bedroom Walls and ceiling No problems were noted. Room was recently repainted, but no indication of previous water damage could be identified.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Master bedroom Closet
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Master bedroom Electrical and lighting Two electrical outlets were incorrectly wired (Open Ground). Recommend licensed electrician make necessary repairs.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Bedroom 2 Doors and windows No problems were found with doors and windows.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Bedroom 2 Floor Floor is carpeted and is in good condition. Room has both input and return HVAC vents.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Bedroom 2 Walls and ceiling No problems were noted. Room was recently repainted, but no indication of previous water damage could be identified.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Bedroom 2 Closet
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Bedroom 2 Electrical and lighting Electrical outlet cover missing. This creates a serious safety hazard and should be replaced.

Photos and Additional Comments